Campaign

16OSD-032

Type:

Recall or Special Service Campaign

Area of Application:

Europe

Subject:

Fuel pressure sensor

Models:

GS300; IS250

Model codes:

GRS190; GSE20

Engine

WHAT IS LEXUS GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. LEXUS retailers / authorized repairers will replace the gasket with a new one and re-install the fuel pressure sensor with the proper tightening torque. The remedy will be performed at NO COST to vehicle owners.

WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	VIN Range			Production Range
		WMI	VDS	VIS	
GS300	GRS190	JTH	BH96S##	0001008-5055682	28/09/2004-03/09/2007
IS250	GSE20	JTH	BK262##	0001003-5053073	03/06/2005-14/09/2007

Note : # indicates that various characters may occupy that position.

IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local Lexus retailers / authorized repairers

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local LEXUS retailer / authorized repairer for confirmation whether their vehicle is involved.
- This incoming Recall or Special Service Campaign will be performed at no cost by any LEXUS retailer / authorized repairer
- Owners are requested to contact their local LEXUS retailer / authorized repairer for diagnosis and repair.

WHEN WILL THIS CAMPAIGN EXPIRE?

This Recall or Special Service Campaign will be available at NO COST to the vehicle owners without time limitation.