



1KBA-044

Campaign

Type:

Recall or Special Service Campaign

Area of Application:

Europe

Subject:

Inverter on Lexus RX400h

Models:

RX400H

Model codes:

MHU38

Engine

WHAT IS LEXUS GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. LEXUS retailers / authorized repairers will replace the Intelligent Power Module (IPM) inside the inverter if required.

WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	VIN Range			Production Period
		WMI	VDS	VIS	
RX400h	MHU38	JTJ	HW31U#	00001030-00049415 02000101-02008127	24 Sep, 2004 through 09 Aug, 2006

Note : # indicates that various characters may occupy that position.

IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local Lexus retailers / authorized repairers

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local LEXUS retailer / authorized repairer for confirmation whether their vehicle is involved.
- This Recall or Special Service Campaign will be performed at no cost by any LEXUS retailer / authorized repairer
- Owners are requested to contact their local LEXUS retailer / authorized repairer for diagnosis and repair.

WHEN WILL THIS CAMPAIGN EXPIRE?

This Recall or Special Service Campaign will be available at NO COST to the vehicle owners without time limitation.

