

 3KB2-021	<h1>Campaign</h1>		
	Type: Recall or Special Service Campaign	Engine	
Area of Application: Europe			
Subject: Inverter on Lexus RX400h			
Models: RX400H			
Model codes: MHU38			

WHAT IS LEXUS GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. LEXUS retailers / authorized repairers will replace the HV IPM / Inverter assembly with a newly designed one.

WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	VIN Range			Production Period
		WMI	VDS	VIS	
<i>RX400h</i>	<i>MHU38</i>	<i>JTJ</i>	<i>HW3###</i>	<i>#0001030 - #2867596</i>	<i>24/09/2004 – 02/12/2008</i>

Note : # indicates that various characters may occupy that position.

IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local Lexus retailers / authorized repairers

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local LEXUS retailer / authorized repairer for confirmation whether their vehicle is involved.
- This incoming Recall or Special Service Campaign will be performed at no cost by any LEXUS retailer / authorized repairer
- Owners are requested to contact their local LEXUS retailer / authorized repairer for diagnosis and repair.

WHEN WILL THIS CAMPAIGN EXPIRE?

This Recall or Special Service Campaign will be available at NO COST to the vehicle owners without time limitation.