


Rear bumper protection plate INSTALLATION INSTRUCTIONS RC



Model year	2014/09
Vehicle code	GSC10*-RCZLHW
Part number	PZ402-C4521-ZB

Revision Record



Rev. No.	Date	Page	Picture	Update	New	Deleted




 3M 751	 3M 2010	 3M VHB SURFACE CLEANER	 adhesion promoter 3M 06396









0-95%








1











16

<p>5 min.</p>	<p>24 h</p>	<p>72 h</p>





Model / Year


RC 2014/09

Rear bumper protection plate

VIN n°

P/N = OK



 = OK

Installation Date:

. . . / . . . /

Technician Name & Signature:

Stamp: