





Side Visor INSTALLATION INSTRUCTIONS LEXUS IS



Model year	2008
Vehicle code	**E20* - *E***W
Part number	08611-53810




Revision Record

Rev. No.	Date	Page	Picture	Update	New	Deleted










5



6

