



Rear bumper protection plate INSTALLATION INSTRUCTIONS CT200h








Model year	2013/12, 2017/08
Vehicle code	ZWA10*-AHX*BW
Part number	PZ402-Z0521-ZB

Revision Record


Rev. No.	Date	Page	Picture	Update	New	Deleted
1	20-09-17	all	all	X		




INFO



1



2



3




Diagram of a car's rear window area with a callout to a wiper blade.





<p>1</p>	<p>< 20°C → 2</p> <p>20°C < 40°C → 7</p>	<p>2</p>
<p>3</p>	<p>20°C < 40°C → 7</p>	<p>INFO</p>


6

Diagram of a wiper blade with a callout to a specific point labeled 'A'.


<p>1</p>	<p>< 20°C → 2</p> <p>20°C < 40°C → 8</p>	<p>2</p>
<p>3</p>	<p>20°C < 40°C → 8</p>	<p>INFO</p>

7







11




12




13




14



15




16




17

18






INFO




24 h



24 h



24 h







CHECK SHEET



Model / Year **CT200h** **2013/12, 201708** Rear Bumper protection plate

VIN n°



Installation Date:

. . / . . /

Technician Name & Signature:

Stamp: